Approved For Release 2000/08/21: CIA-RDP33-02415A000500005

26 June 1964

Dear Jim:

FOIAb3a

FOIAb3a

preliminary report I enclose two copies of operation. This will be followed shortly with equipment and supplies recommendation. I am also sending a copy to

FOIAb3a

There are a few points not over-emphasized in the report that I feel should be called to your attention.

- The IOIC is small and inconveniently laid out and equipped for extensive operations of this type.
- It is probable that future operations will see the 2. ASSC (sponson) area fully occupied by the RA5C program and you may find difficulties in obtaining sufficient space for configuration activities.
- The relative locations of the IOIC, ASSC and vehicle are inconvenient vis-a-vis one another.

FOIAb3a

At the working and lower command levels of the host 4. organization, sensed dissatisfaction with our participation. The comments were heard "we will do all this ourselves next time", "there isn't room for all these people on board if we (the host) are to carry out our own assignments".

FOIAb3a

ELG:atr Encl.

cc: W.G., w/encl.